Article 11

- Appropriate Funds for Little School Roof Replacement/Repair
 - Bond funds for replacement or repair of Little School Roof.
 - See slides to follow
 - Motion by: Selectman O'Leary
 - Presentation by: School Committee
 - BoS recommendation to be made at Town Meeting
 - FinCom recommendation to be made at Town Meeting


Article 11

- E. Ethel Little Elementary School Roof Repair/Replacement
 - A timeline to date:
 - December 24, 2014: The MSBA announces that Statements of Interest (SOI) under the Accelerated Repair Program (ARP) will be accepted beginning on January 9, 2015
 - February 13, 2015: North Reading Submits an SOI for the Little School Roof Project (supported by the Board of Selectmen and School Committee)
 - May 5, 2015: MSBA Personnel Conduct a Site Visit at the Little School
 - June 3, 2015: MSBA Board of Directors Convene to Approve North Reading's SOI
 - June 25, 2015: Finance Committee Approves a Reserve Fund Transfer to Fund the Cost of Feasibility Study and Owner's Project Manager (OPM)
 - August 27, 2015: North Reading is Notified of the Assigned OPM and Architectural Firm to Complete the Feasibility Study
 - September 21 and 22, 2015: Contractors Conduct Requisite Testing at the Little School
 - September 29, 2015: Feasibility Study and Analysis Report with Cost Estimates is Received
 - October 1, 2015: Architect and OPM Conduct a Review of the Feasibility Study and Analysis Report with Town Officials

Article 11

- Review of feasibility study and analysis report, as well as the Town's options, continues.
- A joint meeting of the Board of Selectmen, School Committee, and Finance Committee has been scheduled for Wednesday, October 7th at 7:00 PM at which there will be a review of the feasibility study and analysis report
- Recommend taking up this article at an adjourned Town Meeting continued to Thursday, October 8th at 8:00 PM in the High School Performing Arts Center

Aerial View of the Little School



Project Scope includes Areas A and B identified above; original construction: 1960 and 1968 respectively; these areas were restored in 1990

View of Roof Area A



View of Roof Area A (including cafeteria)



View of Roof Area B



View of Roof Area B (and Gymnasium)



View of Roof Area A



Skylight Deterioration



