

FIRE STATION EXISTING CONDITIONS:

- Health and Safety Conditions**
- Undersized Apparatus Bay**
- Inadequate Sleeping Quarters**
- Inadequate Storage**
- Inefficient and Out of Date Building Systems**
- Building Code Issues to be Addressed**
- Existing Facility Cannot Accommodate Growth**



UNDERSIZED APPARATUS BAY

- ❑ Not Enough Space For All Apparatus Vehicles: Fire Alarm Truck Stored Parks Dept. Barn



Tight Width with Little Space Between Vehicles



Open Doors Conflict with Structure




Use of Vehicle Space to Work on Vehicle Repairs


INADEQUATE SLEEPING QUARTERS



Lack of Privacy, No Accommodation for Female Fire Fighters






Bunk Beds For Additional Addition Personnel





Jury-Rigged Privacy Curtain

INADEQUATE STORAGE



PROPOSED IMPROVEMENTS

- Provide Proper Decontamination Facilities
- Expanded Apparatus Bay



PROPOSED IMPROVEMENTS

- ❑ Inadequate Sleeping Quarters
- ❑ Inadequate Storage

